


CORNER RECORDDocument Number CR 2109City of BerkeleyCounty of Alameda, California

Brief Legal Description _____

**CORNER TYPE**Government Corner ☐ Control ☐Meander ☐ Property ☐Rancho ☐ Other ☒Date of Survey November 10, 2003**COORDINATES (Optional)**

N. _____

E. _____

Zone _____ NAD27 ☐ NAD83 ☐

NAD83 Epoch _____

Elev. _____

Vert. Datum: NGVD29 ☐ NAVD88 ☐Meas. Units: Metric ☐ Imperial ☐
 Corner – Left as found ☒ Found and tagged ☐ Established ☐ Reestablished ☐ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found 3/8" brass pin in standard city monument well. City of Berkeley reference number B1506The monument was referenced by straight lines through the monumentwith distances shown on the diagram.A description of the physical condition of the monument as found and as set or reset: Good condition**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on November 10, 2003Signed [Signature] P.L.S or R.C.E. No. 5003**COUNTY SURVEYOR'S STATEMENT**This Corner Record was received 2-26-04and examined and filed 3-29-04Signed [Signature] P.L.S or R.C.E. No. 5726Title COUNTY SURVEYOR

County Surveyor's Comment _____

